## **MAERSK BINTAN**

IMO No: 9355288 CONTAINER 2008 / 35835 GT

# **COMPANY:**

### YARD INFORMATION:

#### **SCRAPPING INFORMATION:**

Möller A.P., Denmark

Hanjin Heavy Industries Co. Ltd. 186 (South Korea)



North Sea 31/1/2009 © S. Wiedner collection

#### **GENERAL INFORMATION:**

IMO number: 9355288
1st name: MAERSK BINTAN
flag / nationality: Denmark
owner: Maersk Line
operator: Maersk
completion year: 2008

shipyard: Hanjin Heavy Industries Co. Ltd., South Korea

yard / hull number: 186
engine design: B&W
engine type: 8K89MC-C
power output (KW): 28.880
maximum speed (Kn): 22,4
overall length (m): 225,00
overall beam (m): 32,30
maximum draught (m): 12,00
maximum TEU capacity: 3194
container capacity at 14t (TEU): 2542
reefer containers (TEU): 802

deadweight (ton): 43.127 gross tonnage (ton): 36.000 handling gear: None

http://www.containership-info.net.tc

#### **OWNER & FLAG HISTORY:**

MAERSK BINTAN 2008-02-25 LRF HANJIN BUSAN 186 2008-01-21 LRF

Flag Date of record Source Singapore 2008-02-25 LRF

Registered owner Date of record Source

MOLLER SINGAPORE PTE LTD 2008-02-25 LRF

Ship manager Date of record Source MOLLER AP 2005-05-03 LRF

#### SALES, TRANSFERS & RENAMINGS:

MAERSK BINTAN	2008-	Möller Singapore Pte. Ltd., Singapore	

#### **GENERAL VESSEL INFORMATION:**

On 27 February 2008, M.V. **MAERSK BINTAN** (New Building Hull No. N-186) built at Hanjin Heavy Industries & Construction Co. Ltd, Korea was delivered. The 35,849.6 GRT, 3,000 TEU Container Vessel is the first in the series of B-Type container vessels delivered to A.P. Moller Singapore. The vessel is fitted with a HYUNDAI-MAN B&W 8K80 ME-C engine delivering 28,200 KW taking the vessel speed up to 22.1 Knots. **MAERSK BINTAN** is about 212.2 meters long with a beam of 32.2 meters and a depth of 16.56 meters.

http://www.apmsingapore.com.sg/Singapore/News/2008/20080227-MaerskBintan.pdf

Maersk Line has taken in charge the **MAERSK BINTAN**, first of a series of ten ships of 3,400 teu, ordered at Hanjin in two steps (May and Oct 2005). These ships are owned by the Singapore branch of the A.P. Möller-Maersk Group. The **MAERSK BINTAN** is assigned to the new Algeciras-Chile loop launched this month (ANDEAN 2).

 $http://www.axs-alphaliner.com/liner2/research\_files/newsletters/2008/no10/AXS-Alphaliner\%20Newsletter\%20no\%2009\%20-\%202008.pdf$ 

Maersk Line is announcing a number of changes to its Euromed service (43G) serving Northern Europe to the Eastern Mediterranean, which will take effect on 20 July, 2009.

The revised rotation, to commence from vessel **MAERSK BINTAN** 741/0919, will be Felixstowe-Rotterdam-Bremerhaven-Alexandria-Port Said-Haifa-Ashdod-Gioia Tauro to Felixstowe. www.maerskline.com - 9 July 2009

..attempting to leave Bremerhaven under adverse weather conditions on tuesday morning HOEGH LONDON crashed into three

HOEGH LONDON suffered substantial damages to her starboard side, bridge wing, ventilations etc, MAERSK NEWARK's hull was holed at several places, containers fell over board and vsl developed a leakage of one tank. **MAERSK BINTAN** and HUSKY RACER suffered substantial damages too. Alle vessel were detained by the local authorities.

29/5/2009 posted by Fotojoe @www.shipspotting.com

containerships moored at NTB Terminal at Stroomkaje in Bremerhaven.

Last update: 3/1/2010