IMO No: 8406975 CONTAINER 1985 / 11762 GT

**COMPANY:** 

YARD INFORMATION:

**DEMOLITION:** 

RCL Shipmanagement Pte. Ltd.,

Singapore

Korea Shipbuilding & Eng. Corp. 1026 Busan (South Korea)



Singapore 3/2/2010 © S. Wiedner

## **GENERAL INFORMATION:**

Ship's Name: PIYA BHUM

IMO-No.: 8406975 Call Sign: 9VXO Flag: Singapore

Owner: Triple Ford Shipping Pte. Ltd.

Manager: RCL Shipmanagement Pte. Ltd.

Length overall: 147.00 m Registered Length: 136.14 m Registered Breadth: 22.86 m

Draught: 9.662 m Gross Tonnage: 11762 Deadweight: 16356

TEU: 1008

2 Cranes, each 40 t Ship's Speed: 17.20 kn

Shipbuilder: Korea Shipbuilding & Engineering Corporation /

Busan

Yard Number: 1026 Completion: 1985-08

## **OWNER & FLAG HISTORY:**

PIYA BHUM since 01-06-2007 LRF RESOURCEFUL since 01-02-2006 LRF PIYA BHUM since 01-05-2003 LRF RESOURCEFUL during 2002 LRF Flag Date of record Source

Singapore since 01-06-1995 LRF Registered owner Date of record Source

TRIPLE FORD SHIPPING PTE LTD since 29-12-2008 LRF REGIONAL CONTAINER LINES since 01-06-2007 LRF

Ship manager Date of record Source

RCL SHIPMANAGEMENT PTE LTD since 01-01-1996 LRF

## **SALES, TRANSFERS & RENAMINGS:**

PIYA BHUM	1985-02		
RESOURCEFUL	2002-03		
PIYA BHUM	2003-06		
RESOURCEFUL	2006-07		
PIYA BHUM	2007-	Triple Ford Shg. Pte. Ltd., Singapore	

## **GENERAL VESSEL INFORMATION:**

PIYA BHUM 16,356/85 - KSEC - MITSUBISHI 9,200 - 2HO 6HA - C 4X40T - 1,008 TEU

Sold for \$5.9 mill. to undisclosed buyers. www.weberseas.com - January 9th, 2009

Stranded 1/5/2010 about 20 miles N of Surabaya in position 06.53S, 112.44E and during refloating operations the following day , struck a submerged object, sustained damage aft, took water and stranded again. She was on passage from Singapore for Surabaya with containers.

Report by Marine News 8/2010

Last update: 30/12/2010